EXHIBIT A

Hello David

Re: policy CSRYP/202350 VIKING POWER LLC, DOL 8/30/21.

Loss due to: Miss Dunia Fire

My name is Gail Reynolds and I work for New Bedford Inc. our boat was totaled- due to the fire on August 30.2021. We are the owners of Crow Island, our boat is our main transportation of getting our renters over to the house. Our renters count on us to supply all transportation services needed to get them back and forth from the island. Due to the boat being out of commission we have lost all of our income from the island during Sept – Oct 2021 and at this time we have not included Nov 2021.

Attached you will find the cost of the loss of boat: 87,000

Loss of income 35,000

Insurance check we received -47,000

The total loss for this boat at this time: 75,000

If you have any question please email or call me at the number below.

Thank you,

Gail Reynolds
Executive Administrator

Email: qail@newbedfordinc.com

New Bedford Inc. 508.999.7262

Any personal data acquired, processed or shared by us will be lawfully processed in line with applicable data protection legislation. If you have any questions regarding how we process personal data refer to our Privacy Notice https://www.sedgwick.com/global-privacy-policy. Any communication including this email and files/attachments transmitted with it are confidential and are intended solely for the use of the individual or entity to whom they are addressed. If this message has been sent to you in error, you must not copy, distribute or disclose of the information it contains and you must notify us immediately (contact is within the privacy policy) and delete the message from your system.



VESSEL OWNER'S OR MASTERS STATEMENT OF LOSS

Claim No. 0AB339751
Dated SEPTEMBER 22 2021 at 1100 in
I, ALBERT J. SHNTOS am the Owner / Master
of the Vessel 2005 25' STANCEY Registration No. MS 4743 BN
My address is: 38 BETHEL ST NEW BEOFORD MA 02740
On the 36 day of Avoid 7 2021, at approximately
4:00 o'clock M., while located at TLEFT MARINA
the above vessel and / or person(s) met with an accident, or injury, the circumstances of which are in detail as follows: HISS DINIA PLEASURE BOAT (ALGII ON FIRE MY VESSEL WAS AT SAME DOLL FUEL SPILLED INTO OCEAN LITON FIRE SURROUNDED MY VESSEL INTENSE HEAT GIVED IT TO WARR
The damage directly caused to said vessel by this accident is as follows: (Describe in detail all parts of the vessel which were damaged and the extent of the damage, or attach survey if available). WHERE DURING BIOKEN GLASS METER WIRING
The damage to said vessel may be inspected at BATINE MARINE BOATTAN SILVE ST. DE BEDTOILD MA 0.0744 Cost of repairs has been estimated at \$ 87,000 %xx
by: PRECISION MARINE SERVICE JUST HORKOS (Name of repair yard and attach written estimate, if possible) 774-366 7188

Name and Address	Type of c	damage or injur	y Esti	Estimated Amount	
Other vessels in the vicinity wer	e:	(Giv	ve names or describe)		
The names and permanent addre	esses of witness,	including the cr	rew of said vessel are	e listed below:	
Witness			Addre	ess	
At the time of the loss the vessel Free and clear, with no encumbrical Policy No. B 5 T H 512	was owned by ances on same a	and there was no	insurance other than	1	
Except as follows: (list any encu	mbrances and or	ther insurance p	olicies).		
All facts material to the question withheld. (Note: Attach surveys, statements. In case of collision a	estimates, state	ments of witnes:	ses, photographs and	other material	
		0.1			
Neither the furnishings of this fo constitutes admission of liability	rm nor acceptan by said Compar	ice of the comple	eted statements by the	ie Insurance Company	



Marine Safety Consultants, Inc.

26 Water Street, P.O. Box 615, Fairhaven, MA 02719-0615 Phone: 508-996-4110 • Fax: 508-990-2094 www.marinesafetyconsultants.com

> Date: September 13, 2021 File No.: 21-0760

Intact Insurance One State Street, 31st Floor New York, NY 10004

Attn: Sylvia Scott

VESSEL CASUALTY LOSS AND DAMAGE SURVEY

VESSEL: "Crow Island" DATE OF LOSS: August 30, 2021

REG. NO.: MS 4743 BN COMPANY: Intact

INSURED: New Bedford, Inc. CLAIM NO.: OAB339756

Report of survey conducted by the undersigned on September 2, 2021, and subsequent dates at the request of Sylvia Scott for the purpose of ascertaining the cause, nature, and extent of damages alleged to have been sustained by the subject vessel in consequence of being heat damaged by a burning vessel at the same dock location.

There were no personal injuries involved with this casualty.

The survey was conducted aboard the vessel while hauled ashore on dry land supported by keel blocking and boat stands at Bayline Marine in New Bedford, MA.

The case was assigned to us on September 2, 2021.

VESSEL DESCRIPTION

The insured vessel is a 2005 27' Stanley built in the landing craft configuration bearing hull identification number QMJ70298C505 powered by a single 2005 225 HP Yamaha outboard engine bearing serial number 69JX1020182N and model number F225TXRD.

New Bedford, Inc. Page 2 of 3

FOUND

File No.: 21-0760

CIRCUMSTANCES OF INCIDENT:

The facts and circumstances surrounding this incident are summarized as follows:

On the date of loss, the insured vessel was secured to the dock at the Fleet Marina in New Bedford, MA adjacent to a 2008 82' Horizon motor yacht that caught fire, burned extensively and sank. During the fire that lasted several hours the insured vessel was exposed to intense heat resulting in deflection of the aluminum hull along the starboard side.

DAMAGES FOUND

When the undersigned attended the aboard vessel inspection the following damages were found, and recommendations made:

RECOMMEND

Replace the name and registration

1.	The starboard side hull plating is discolored and distorted due to exposure to heat.	1.	Replace the distorted starboard hull side plating.
2.	The starboard side of the deck is distorted due to exposure to heat.	2.	Replace the distorted starboard side decking.
3.	Two of the starboard side cabin windows are cracked.	3.	Replace the two cracked windows.
4.	The VHF radio antenna is heat 4 damaged.		Replace the VHF antenna.
5.	The navigation lights are	5.	Replace the navigation lights.

CAUSE OF DAMAGES

discolored.

The decals for the vessel's name

and registration are burnt.

It is the opinion of the undersigned surveyor that the cause of damages to the insured's vessel was a direct result of heat exposure from the burning vessel Miss Dunia.

5.

decals.

SUBROGATION

5.

There appears to be potential for subrogation as the damage to the vessel is the result of heat generated by the fire that took place on the vessel Miss Dunia.

New Bedford, Inc. File No.: 21-0760

Page 3 of 3

DEDATES

<u>REPAIRS</u>

As of the time of this report the vessel remains at Bayline Boatyard awaiting repair.

COST OF REPAIRS

As of the time of this report an estimate for repair has not yet been written or obtained. However, based on the scope of damage noted at the time of inspection I suggest setting the reserve at the policy limit.

RECOMMENDATIONS/FUTURE PLANS

1. Upon review of this report it should be determined if there is coverage for this loss under the terms and conditions of the insured's policy.

2. If the insured's claim is accepted, I recommend he provide me with all estimates and or invoices associated with the repair. Once I have reviewed the estimates/invoices related to this loss I will forward my comments and recommendations to you to further the claims process.

3. I plan to place my file in diary until such time I receive the foregoing documents for my review.

Please do not hesitate to contact this office with any questions, concerns, or further instructions.

Submitted without prejudice, MARINE SAFETY CONSULTANTS, INC.

Christopher R. MacDougall Senior Marine Surveyor

Enclosures:

1. Photographs